

Glass tops

Installing glass conference table tops

- Before installation, clean and top and sub-top surfaces and dry them with a lint-free cloth. Remove grime if necessary using a rag with rubbing alcohol.
- Supplied bumpers should be applied to the sub-top at the edges and corners of where each glass panel will rest. Spacing between bumpers should be no more than 2 feet apart along the edges and across the middle of each glass top segment
- Clean and dry sub-top at each bumper location before removing the bumpers backing and applying their adhesive sides
- Install the top segments* with glass-handling PODS and avoid touching surfaces

*Note the “Install this side up” labels on the glass panels

